OPTIONAL FORM NO. 10 MAY 1962 EDITION GSA FPMR (41 CFR) 101-11.6

UNITED STATES GOVERNMENT

Memorandum

	TITO I WILL WILL	
то :	Director of Communications	OCE-M77-011 DATE: 5 January 19
25X1 _{ROM} :	Chief, Communications Engineering	
SUBJECT:	Monthly Narrative Summary ReportDec	cember 1976
25X1 25X1	An agreement was reached for a firm f	TS-W on 16 December.
	2. The CDS preacceptance test sand is still in progress.	started on 18 December
	3. DBA Systems advised OL/PD or first AFT system will not be complete revised project and delivery schedule from DBA on 15 January 1977.	ed on schedule. A
25X1		
	5. Program effort leading to post- SC-3 small satellite field terminal intense pace. The pre-bidders' confusion 4 January 1977. The proposal due da	erence took nlace on
	6. As of 31 December 1976, onfirst SKYMUX station between The end result will be the first ope station.	began.
	7. The equipment and wiring pa SKYMUX installation was shipped in m	ckage for the
	8. Members of the Narrowband S Group collected their final data and reports of findings and recommendati Group was split into three principal microwave study, and an audio study, Secure Voice Operator's position at	ons. The Working inal investigations: a and a review of the



ONIDENTIAL

25X1

25X1

25X1

25X1

77

SUBJECT: Monthly Narrative Summary Report--December 1976

25X1

25X1

25X1

25X1

25X1

- 10. CED completed a Class "A" evaluation of the last of four tactical type transceivers as requested by COD, in support of an ____ requirement. The four transceivers evaluated were the SouthCom SC-130D, Racal TRA-931, Plessey PRC-320, and the Collins 719D.
- 11. The external contract with for testing and repair of TAR-224 units was completed 15 December 1976. A total of 215 units were tested. One hundred and seventy-eight units were repaired, accepted, and returned to Allocation-55 stock. Thirty-seven units were not economically repairable.
- 12. Action was initiated to convert Band B and C field transmitters to the RT/A-803 Model to support field requirements until the RS-804 follow-on system is available.
- 13. CED technical and operational evaluation of the Telcom 3061 receive system was suspended due to a temperature problem. The system has been returned to Telcom for rework of a temperature sensitive circuit.
- 14. Hughes delivered a proposal, with several options, for modification of their 44440H Millimeter Wave Communicator.
- 15. Representatives of 3M demonstrated their Model 666 digital facsimile machine. Quality Assurance Branch testing has been delayed due to a mechanical problem in a set of drive-shaft gears.
- 16. All new Timeplex MX-113 equipment has been inspected. To date the T&I shop has expended approximately 600 man hours testing this equipment.
- 17. The crypto repair unit is making an effort to increase the ready-for-issue stock of KW-7 units. Higher-than-expected power supply failures and covers with gasket material missing are the two major problem areas encountered.

25X1

Approved For Release 2007/10/23 : CIA-RDP78-02820A001400090011-4

25X1

25X1

SUBJECT: Monthly Narrative Summary Report--December 1976

25X1

25X1

18. Three sets of SKYLINK terminal spares were ordered sent from the ______ for test and inspection at _____ In the future, _____ will maintain a stock level of three T&I'ed spares at all times.

Distribution:
Origina* - D/CO; DD/CO; OC-EXA; OC-P&B; OC-IC (Archives)
1 - OC-O; OC-O/D
1 - OC-S; OC-CS